



# CLUTCHTECH



## TSB-253

### Suzuki Swift Cross Shaft

In some Suzuki Swifts, the cross shaft can develop a crack, such as the one shown in the image below.



Any damage to the cross shaft can cause the bearing to run off centre and lead to premature wear on the clutch.

It is therefore highly recommended that all parts of the clutch system are inspected each time the gearbox is removed and any parts that are damaged/ worn are replaced prior to reassembly.

You can purchase a new cross shaft and bushes from your nearest ClutchPro Distributor.

**Cross shaft:** ATFSZ01-CS

**Bushes:** ATFSZ01-CS1, ATFSZ01-CS2

#### LEADING BRANDS

CLUTCHPRO CLUTCHPRO



[australianclutch.com.au](http://australianclutch.com.au)

1800 CLUTCH (258824)